VEHICLE HISTORY REPORT

Sample Vehicle Report — Mid-Size Crew Cab Pickup

VIN: SAMPLE-VIN-00000000 | Crew Cab | Pickup Truck

Report Summary

● CLEAR **Accident Records**

No accident records were found for this vehicle in the available databases. Some incidents may not be captured if they weren't reported to official sources.

● CLEAR **Flood Damage**

No flood records were found for this vehicle in the available databases. If an incident wasn't reported to insurance or government agencies, some records might be missing.

● CLEAR **Theft Records**

No theft records were found for this vehicle. If a theft wasn't reported to law enforcement or official databases, the record may not appear.

● CLEAR **Salvage / Total Loss**

No salvage records were found for this vehicle. If the vehicle has been processed by multiple agencies, some records may not be available.

● CLEAR **Manufacturer Recalls & Defects**

No recalls or safety defects were found for this vehicle in the available databases.

● CLEAR **Historical Sale Records**

No historical sale listings were found for this vehicle in the available databases. Private-party sales or sales through non-reporting sources may not appear.

● CLEAR **Owner Reviews**

No owner reviews have been submitted for this specific VIN yet (0.00 rating based on 0 reviews).

Vehicle Information

Year	20XX
Make	Sample Make
Model	Sample Model
Trim	–
Style	Crew Cab
Type	Pickup Truck
Category	Standard Pickup Truck

Manufacturing Details

Made In	Sample Country
Manufacturing City	Sample City

Dimensions

Doors	4-Door
Curb Weight	–
Gross Vehicle Weight Rating	–
Overall Height	XX.XX inches
Overall Length	XXX.XX inches
Overall Width	XX.XX inches
Wheelbase Length	XXX.XX inches
Standard Seating	6

SAMPLE REPORT
FOR ILLUSTRATION PURPOSES ONLY

Engine & Performance

Engine	Sample V8
Engine Size	X.XL
Engine Cylinders	8
Transmission	6-Speed Automatic
Transmission Type	Automatic
Transmission Speeds	6-Speed
Drivetrain	Four-Wheel Drive

Additional Features

Anti-Brake System	4-Wheel ABS
Steering Type	Recirculating

Pricing (When New)

Manufacturer Suggested Retail Price (MSRP)	$XX,XXX
Invoice Price	$XX,XXX
Delivery Charges	$X,XXX

SAMPLE REPORT
FOR ILLUSTRATION PURPOSES ONLY

Equipment & Features

ANTI-THEFT & LOCKS

Child Safety Door Locks	Standard
Power Door Locks	Standard
Vehicle Anti-Theft	Standard

BRAKING & TRACTION

ABS Brakes	Standard
Traction Control	Standard
Vehicle Stability Control System	Standard

SAFETY

Driver Airbag	Standard
Front Side Airbag	Standard
Passenger Airbag	Standard
Side Head Curtain Airbag	Standard

REMOTE CONTROLS, RELEASE & CLIMATE CONTROL

Keyless Entry	Standard
Air Conditioning	Standard
Separate Driver/Front Passenger Climate Controls	Standard

SAMPLE REPORT
FOR ILLUSTRATION PURPOSES ONLY

INTERIOR FEATURES

Cruise Control	Standard
Tachometer	Standard
Leather Steering Wheel	Standard
Steering Wheel Mounted Controls	Standard
Telescopic Steering Column	Standard
Adjustable Foot Pedals	Standard
Tire Pressure Monitor	Standard
Trip Computer	Standard

ENTERTAINMENT, COMMUNICATION & NAVIGATION

AM/FM Radio	Standard
Navigation Aid	Standard

SAMPLE REPORT
FOR ILLUSTRATION PURPOSES ONLY

SEAT

Driver Multi-Adjustable Power Seat	Standard
Front Heated Seat	Standard
Front Power Lumbar Support	Standard
Front Split Bench Seat	Standard
Passenger Multi-Adjustable Power Seat	Standard

ROOF / EXTERIOR FEATURES

Power Sunroof	Optional
Splash Guards	Optional

EXTERIOR LIGHTING

Daytime Running Lights	Standard
Fog Lights	Standard

TIRES & WHEELS

Alloy Wheels	Standard
Chrome Wheels	Standard
Steel Wheels	Optional
Tires	LT265/70R18

MIRRORS, WINDOWS & WIPERS

Power Windows	Standard
Electrochromic Interior Rearview Mirror	Standard
Interval Wipers	Standard
Rear Window Defogger	Standard

SAMPLE REPORT
FOR ILLUSTRATION PURPOSES ONLY

CHASSIS

Front Brake Type	Disc
Rear Brake Type	Disc
Front Suspension	Independent
Rear Suspension	Live
Front Spring Type	Torsion Bar
Rear Spring Type	Leaf

SAMPLE REPORT
FOR ILLUSTRATION PURPOSES ONLY

INTERIOR DIMENSIONS

Front Headroom	XX.XX in.
Rear Headroom	XX.XX in.
Front Legroom	XX.XX in.
Rear Legroom	XX.XX in.
Front Shoulder Room	XX.XX in.
Rear Shoulder Room	XX.XX in.
Front Hip Room	XX.XX in.
Rear Hip Room	XX.XX in.

EXTERIOR DIMENSIONS, CARGO & CAPACITY

Overall Length	XXX.XX in.
Overall Width	XX.XX in.
Overall Height	XX.XX in.
Wheelbase	XXX.XX in.
Ground Clearance	X.XX in.
Cargo Bed Overall Length	XXX.XX in.
Standard Seating	6

Fuel Efficiency

Fuel Type	Diesel
Fuel Capacity	XX.XX gallons
City Mileage	–
Highway Mileage	Not available

SAMPLE REPORT
FOR ILLUSTRATION PURPOSES ONLY

Safety Ratings

No official safety ratings were found for this vehicle in the available databases. These records typically reflect crash-test results and safety evaluations conducted by official agencies; if a vehicle hasn't been tested or the data hasn't been published, ratings may not be available.

SAMPLE REPORT
FOR ILLUSTRATION PURPOSES ONLY

Current Warranty Status

Basic — Original Warranty	36 months / 36,000 miles (Expired)
Powertrain — Original Warranty	60 months / 60,000 miles (Expired)
Rust — Original Warranty	72 months / 100,000 miles (Expired)

Ownership Cost

This section illustrates where a narrative summary of estimated running costs — insurance, fuel, and maintenance — appears in your delivered report, based on the specific vehicle's class, engine, and drivetrain.

Auto Insurance Outlook

This section illustrates where a general insurance cost outlook for the vehicle's class and safety profile appears in your delivered report.

Estimated Market Value

This section illustrates where an estimated market value range — based on original MSRP, mileage, condition, and current used-market listings — appears in your delivered report.

Note: market value estimates depend on sufficient comparable listing data being available for the specific vehicle.

SAMPLE REPORT
FOR ILLUSTRATION PURPOSES ONLY

How It Compares to Similar Vehicles

This section illustrates where your delivered report compares the vehicle against similar competing models in its class — covering performance, features, ride comfort, reliability reputation, and pricing position.

Commonly Reported Issues

This section illustrates where your delivered report summarizes commonly reported issues for the vehicle's specific year, make, and model — covering areas such as electronics, drivetrain, and any relevant recall history.

This is a sample report generated by Prime Auto Inspection to illustrate report layout and content coverage. It does not represent any real vehicle. Your actual report will be compiled using your vehicle's real VIN and specification data.

SAMPLE REPORT
FOR ILLUSTRATION PURPOSES ONLY

Data Sources

This report draws on multiple third-party and public data sources to compile the vehicle history, specification, and market information presented above. Coverage and completeness can vary by vehicle, region, and how consistently an event was reported to the source in question.

Title & Brand History	State Department of Motor Vehicles (DMV) title records and the National Motor Vehicle Title Information System (NMVTIS).
Accident, Damage & Salvage Records	Insurance industry loss and claims databases, salvage and total-loss auction records, and state-reported damage disclosures.
Theft Records	Law enforcement and national stolen-vehicle databases.
Flood Damage	Insurance flood-loss databases and disaster/flood-zone reporting agencies.
Manufacturer Recalls & Defects	National Highway Traffic Safety Administration (NHTSA) recall and safety defect records, and manufacturer service bulletins.
Vehicle Specifications & Equipment	Original manufacturer specification data and factory build/equipment records.
Sales, Ownership & Registration History	State registration records and reported dealership, auction, or marketplace listing history, where available.
Market Value & Pricing	Aggregated listing and transaction data from the used-vehicle marketplace.
Warranty Status	Original manufacturer warranty terms, estimated against vehicle age and reported mileage.

SAMPLE REPORT
FOR ILLUSTRATION PURPOSES ONLY

Note: not every event affecting a vehicle is guaranteed to be captured by these sources. An incident that was never reported to insurance, law enforcement, or a government agency may not appear in this report. This report should be used as one part of a broader evaluation, alongside a professional physical inspection where possible.

Disclaimer of Accuracy

The information contained in this report has been compiled from third-party data providers and publicly available sources. While Prime Auto Inspection makes reasonable efforts to ensure the accuracy and completeness of this information, no guarantee, warranty, or representation — express or implied — is made as to the accuracy, completeness, or reliability of the data presented. This report is provided strictly for general informational purposes and should not be relied upon as the sole basis for any purchase, sale, financing, or other decision. Prime Auto Inspection shall not be held liable for any loss or damage arising from reliance on this report.

Payment & Refund Policy

Once an order for this report is placed and payment is received, report generation and processing begins immediately upon confirmation. A confirmation email is issued at this stage. As processing commences at the point of order confirmation, all payments are non-refundable, regardless of the findings contained in the completed report.

For questions regarding this report, contact info@primeautoinspection.com

SAMPLE REPORT
FOR ILLUSTRATION PURPOSES ONLY